

Mining Report

MINE ID: M0270007

MINE NAME: DRUM MINE

OPERATOR: JUMBO MINING COMPANY

CONTACT: DAVE HARTSHORN ADDRESS: P O BOX 999

DELTA UT 84624

PHONE: () - 801

Surface Owner: BLM

BLM #: UTU-063447

Mineral Owner: BLM Lease #:

Qtr-Qtr-Qtr1 Qtr-Qtr1 Qtr1 Qtr-Qtr-Qtr2 Qtr-Qtr2

Town Range Sec 15.0S 10.0W

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: S

Mine Status (PRO, ACT, SUS, RET): SUS

Acreage: 137

Minerals Mined

AU

DATE RECEIVED	TENTATIVE APPROVAL DATE	FINAL APPROVAL DATE	LAST INSPECTED
07/08/83	10/03/83	11/28/83	04/14/93

BOND TYPE: U S TREASUREY BILLS

BOND AMOUNT: \$\$\$\$165,000

ANNUAL REPORT YEAR: 93

1		YTD	Total				
NON	COMP NOTICES:	0	0	DATE ISSUED:	/	1	DATE RESOLVED: / /
I	VIOLATIONS:	0	0	DATE ISSUED:	1	1	DATE RESOLVED: / /
	REVISIONS:	0	0	DATE REC'D:	1	1	DATE APPROVED: / /
	AMENDMENTS:	0	0	DATE REC'D:	1	1	DATE APPROVED: / /

COMMENTS:

DRUM MINE CLOSED DOWN BY THE DEPT OF ENVIRONMENTAL QUALITY FOR HEAP LEACH DUMPS LEAKING. JUMBO ATTEMPTED TO USE 2 OTHER DUMPS UNDER THE AUTHORITY OF WESTERN STATES MINERALS, BUT WSM REFUSED JUMBO ACCESS. OPERATOR TRYING TO DEVELOP A NEW HEAP LEACH FACILITY (IN PERMITTING PROCESS). HEAP LEACH #7 WAS RESEEDED. OPERATOR RECLAIMED (SEEDED) +20 ACRES DURING 1992. INSPECTION MADE SPRING OF 1993 TO BETTER FAMILARIZE DOGM & BLM W/CURRENT STATE OF SITE. MEMO DATED 4/21 IN FILE.